

Edition 1.0 2020-11

# TECHNICAL SPECIFICATION



Measurement of internal electric field in insulating materials – Pressure wave propagation method

INTERNATIONAL ELECTROTECHNICAL COMMISSION

ICS 17.220.99; 29.035.01

ISBN 978-2-8322-8993-8

Warning! Make sure that you obtained this publication from an authorized distributor.

# CONTENTS

INTRODUCTION 6 1 Scope 7 2 Normative references 7 3 Terms, definitions and abbreviated terms 7 3.1 Terms and definitions. 7 3.2 Abbreviated terms 7 4 Principle of the method 8 5 samples 10 6 Electrode materials. 7 9 Calibrating the electric field 10 9 Calibrating the electric field 11 9 Calibrating the electric field 11 9 Calibrating the electric field 11 10 Measurement procedure 11 11 Data processing for the experimental measurement. 13 12 Measurement examples 14 12.1 Samples 14 12.2 Pressure pulse generation 14 12.3 Calibration of sample and signal 14 12.4 Testing sample and experimental results 15 Annex A (informative) Preconditional method of the original signal for the PWP method 19 A.1 Simple integration limitation 19 A.2 Analysis of the correction procedure 01 A Estimation of the correction procedure 02 A.3 Example of the correction procedure 03 Annex A (informative) Linearity verification of the measuring system 26 B.1 Linearity verification procedure 20 A.3 Example of the correction coefficients 22 A.5 MATLAB® code 24 Annex B (informative) Linearity verification of the measuring system 26 B.1 Linearity verification procedure 26 B.3 Linearity verification procedure 26 B.4 Example of linearity verification 26 B.5 Linearity verification 26 B.4 Example of linearity verification 26 B.4 Example of linearity verification 26 B.4 Example of linearity verification 26 B.5 Figure 3 - Sample circuit to protect the amplifier from damage by a small discharge on the sample 15 Figure 5 - First measured current signal under -5,8 kV 16 Figure 9 - Internal electric field distribution under -46,4 kV, at the initial state 17 Figure 9 - Internal electric field distribution under -46,4 kV, at the initial state 17 Figure 9 - Internal ele	FOREV	VORD	4		
2     Normative references     7       3     Terms, definitions and abbreviated terms     7       3.1     Terms and definitions     7       3.2     Abbreviated terms     7       3.1     Terms and definitions     7       3.2     Abbreviated terms     7       3.2     Abbreviated terms     7       3.1     Terms and definitions     7       3.2     Abbreviated terms     7       3.2     Abbreviated terms     7       4     Principle of the method     8       5     Samples     10       6     Electrode materials     10       7     Pressure pulse wave generation     10       8     Set-up of the measurement.     11       9     Calibration of samples     14       12.1     Samples     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19	INTRO	INTRODUCTION			
3     Terms, definitions and abbreviated terms     7       3.1     Terms and definitions.     7       3.2     Abbreviated terms     7       4     Principle of the method.     8       5     Samples.     10       6     Electrode materials.     10       7     Pressure pulse wave generation.     10       8     Set-up of the measurement.     11       9     Calibrating the electric field     12       10     Measurement procedure.     12       11     Data processing for the experimental measurement.     13       12     Measurement examples.     14       12.1     Samples.     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method.     19     A.1     Simple integration limitation     19       A.2     Analysis of the resiliency effect and correction procedure on a PE sample     21       A.4     Estimation of the correction nor	1 Sc	cope	7		
3.1     Terms and definitions	2 No	ormative references	7		
3.2     Abbreviated terms     7       4     Principle of the method     8       5     Samples     10       6     Electrode materials     10       7     Pressure pulse wave generation     10       8     Set-up of the measurement     11       9     Calibrating the electric field     12       10     Measurement procedure     12       11     Data processing for the experimental measurement     13       12     Measurement examples     14       12.1     Samples     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19     A.1     Simple integration limitation     19       A.1     Simple of the correction procedure on a PE sample     21     A.4       A analysis of the resiliency effect and correction procedure     20     A.4     Estimation of the correction procedure     26       B.1     Linearity verification     26	3 Те	erms, definitions and abbreviated terms	7		
4     Principle of the method.     8       5     Samples     10       6     Electrode materials.     10       7     Pressure pulse wave generation     10       8     Set-up of the measurement.     10       9     Calibrating the electric field     12       10     Measurement procedure     12       11     Data processing for the experimental measurement.     13       12     Measurement examples     14       12.1     Samples.     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19     A.1     Simple integration limitation       A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative) Linearity verification <t< td=""><td>3.1</td><td>Terms and definitions</td><td>7</td></t<>	3.1	Terms and definitions	7		
5     Samples     10       6     Electrode materials     10       7     Pressure pulse wave generation     10       8     Set-up of the measurement.     11       9     Calibrating the electric field     12       10     Measurement procedure     12       11     Data processing for the experimental measurement.     13       12.1     Samples     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method	-				
6     Electrode materials     10       7     Pressure pulse wave generation     10       8     Set-up of the measurement.     11       9     Calibrating the electric field     12       10     Measurement procedure     12       11     Data processing for the experimental measurement.     13       12     Measurement examples     14       12.1     Samples     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19     A.1     Simple integration limitation     19       A.2     Analysis of the resiliency effect and correction procedure     20     A.3     Example of the correction coefficients     22       A.5     MATLAB® code     24     Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification procedure     26     26     26       B.4     Example of linearity verification     26     26     24					
7     Pressure pulse wave generation     10       8     Set-up of the measurement.     11       9     Calibrating the electric field     12       10     Measurement procedure     12       11     Data processing for the experimental measurement.     13       12     Measurement examples     14       12.1     Samples     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19     A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21     A.4     Estimation of the correction coefficients     22       A.5     MATLAB® code     24     Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification procedure     26     B.3     Linearity verification procedure     26       B.4     Example of linearity verification     26     B.3     Linearity verification					
8     Set-up of the measurement     11       9     Calibrating the electric field     12       10     Measurement procedure     12       11     Data processing for the experimental measurement.     13       12     Measurement examples     14       12.1     Samples     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19       A.1     Simple integration limitation     19       A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification procedure     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification </td <td>6 El</td> <td>ectrode materials</td> <td>. 10</td>	6 El	ectrode materials	. 10		
9     Calibrating the electric field     12       10     Measurement procedure     12       11     Data processing for the experimental measurement     13       12     Measurement examples     14       12.1     Samples     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19       A.1     Simple integration limitation     19       A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative)     Linearity verification     26       B.1     Linearity verification     26       B.3     Linearity verification procedure     26       B.4     Example of the PWP method     11       Figure 1 – Principle of the PWP method     11	7 Pr	essure pulse wave generation	. 10		
10     Measurement procedure     12       11     Data processing for the experimental measurement     13       12     Measurement examples     14       12.1     Samples     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19       A.1     Simple integration limitation     19       A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification     26       B.3     Linearity verification     26       B.4     Example of cincuit to protect the amplifie		·			
11     Data processing for the experimental measurement.     13       12     Measurement examples.     14       12.1     Samples.     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19       A.1     Simple integration limitation     19       A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification     26       B.2     Sample conditions.     26       B.3     Linearity verification     26       B.4     Example of linearity verification     11       Figure 1 – Principle of the PWP method     11       Figure 3 – Sample of circuit to protect the amplifier from damage by a sm	9 Ca	alibrating the electric field	. 12		
12     Measurement examples     14       12.1     Samples     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19       A.1     Simple integration limitation     19       A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative)     Linearity verification of the measuring system     26       B.1     Linearity verification procedure     26       B.2     Sample conditions.     26       B.3     Linearity verification procedure     26       B.4     Example of the PWP method     11       Figure 1 – Principle of the PWP method     11       Figure 2 – Measurement set-up for the PWP method     11       Figure 3 – Sample of circuit to protect the amplifier from damage b	10 Me	easurement procedure	. 12		
12.1     Samples.     14       12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19       A.1     Simple integration limitation     19       A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative)     Linearity verification of the measuring system     26       B.1     Linearity verification procedure     26       B.2     Sample conditions     26       B.3     Linearity verification procedure     26       B.4     Example of the PWP method     11       Figure 1 – Principle of the PWP method     11       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First me	11 Da	ata processing for the experimental measurement	. 13		
12.2     Pressure pulse generation     14       12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19       A.1     Simple integration limitation     19       A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative)     Linearity verification of the measuring system     26       B.1     Linearity verification     26       B.2     Sample conditions     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification     26       B.4     Example of the PWP method     11       Figure 1 – Principle of the PWP method     11       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge     11       Figure 4 – Measured current signal under –5,8 kV     14       Figur	12 Me	easurement examples	. 14		
12.3     Calibration of sample and signal     14       12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP       method     19       A.1     Simple integration limitation     19       A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification     26       B.2     Sample conditions     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification     11       Figure 3 – Sample of	12.1	Samples	. 14		
12.4     Testing sample and experimental results     15       Annex A (informative)     Preconditional method of the original signal for the PWP     19       A.1     Simple integration limitation     19       A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative)     Linearity verification of the measuring system     26       B.1     Linearity verification     26       B.2     Sample conditions     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification     26       B.4     Example of linearity verification     26       B.4     Example of linearity verification     26       B.4     Example of the PWP method     11       Figure 1 – Principle of the PWP method     11       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First measured current signa					
Annex A (informative) Preconditional method of the original signal for the PWP     19       Mathematical Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification     26       B.2     Sample conditions     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification     26       B.4     Example of circuit to protect the amplifier from damage by a small discharge     11       Figure 1 – Principle of the PWP method     11     11       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure					
method     19       A.1     Simple integration limitation     19       A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification     26       B.2     Sample conditions     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification     11       Figure 1 – Principle of the PWP method     9     9       Figure 2 – Measurement set-up for the PWP method     11       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First measur			.15		
A.2     Analysis of the resiliency effect and correction procedure     20       A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification     26       B.2     Sample conditions     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification     26       B.4     Example of conditions     26       B.4     Example of linearity verification     26       Figure 1 – Principle of the PWP method     11     11       Figure 2 – Measurement set-up for the PWP method     11       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge on the sample     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First measured current signal under –46,4 kV, after 1,5 h under			. 19		
A.3     Example of the correction procedure on a PE sample     21       A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification     26       B.2     Sample conditions     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification     26       Figure 1 – Principle of the PWP method     11     11       Figure 2 – Measurement set-up for the PWP method     11     11       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge on the sample     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First measured current signal under –46,4 kV, after 1,5 h under high voltage     15       Figure 7 – Measured current signal	A.1	Simple integration limitation	. 19		
A.4     Estimation of the correction coefficients     22       A.5     MATLAB <sup>®</sup> code     24       Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification     26       B.2     Sample conditions     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification     26       Figure 1 – Principle of the PWP method     9     9       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First measured current signal under –46,4 kV, after 1,5 h under high voltage     15       Figure 7 – Measured current signal without applied voltage, after 1,5 h under high voltage     16       Figure 8 – Internal electric field distribution under –5,8 kV     16	A.2				
A.5     MATLAB <sup>®</sup> code     24       Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification     26       B.2     Sample conditions     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification     26       B.4     Example of linearity verification     26       B.4     Example of linearity verification     26       Figure 1 – Principle of the PWP method     9       Figure 2 – Measurement set-up for the PWP method     9       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First measured current signal (< 1 min)	A.3	Example of the correction procedure on a PE sample	.21		
Annex B (informative) Linearity verification of the measuring system     26       B.1     Linearity verification     26       B.2     Sample conditions     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification     26       Figure 1 – Principle of the PWP method     9       Figure 2 – Measurement set-up for the PWP method     11       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge on the sample     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First measured current signal under –46,4 kV, after 1,5 h under high voltage     15       Figure 7 – Measured current signal without applied voltage, after 1,5 h under high voltage     16       Figure 8 – Internal electric field distribution under –5,8 kV     16	A.4				
B.1     Linearity verification     26       B.2     Sample conditions     26       B.3     Linearity verification procedure     26       B.4     Example of linearity verification     26       Figure 1 – Principle of the PWP method     26       Figure 2 – Measurement set-up for the PWP method     9       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge on the sample     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First measured current signal (< 1 min)	A.5	MATLAB <sup>®</sup> code	. 24		
B.2     Sample conditions	Annex	B (informative) Linearity verification of the measuring system	.26		
B.3     Linearity verification procedure     26       B.4     Example of linearity verification     26       Figure 1 – Principle of the PWP method     26       Figure 2 – Measurement set-up for the PWP method     9       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge on the sample     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First measured current signal (< 1 min)	B.1	•			
B.4     Example of linearity verification.     26       Figure 1 – Principle of the PWP method.     9       Figure 2 – Measurement set-up for the PWP method     11       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge on the sample.     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First measured current signal (< 1 min)					
Figure 1 – Principle of the PWP method     9       Figure 2 – Measurement set-up for the PWP method     11       Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge on the sample     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First measured current signal (< 1 min)					
Figure 2 – Measurement set-up for the PWP method11Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge on the sample11Figure 4 – Measured current signal under –5,8 kV14Figure 5 – First measured current signal (< 1 min)	В.4	Example of linearity verification	.20		
Figure 2 – Measurement set-up for the PWP method11Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge on the sample11Figure 4 – Measured current signal under –5,8 kV14Figure 5 – First measured current signal (< 1 min)	Figure	1 – Principle of the PWP method	9		
Figure 3 – Sample of circuit to protect the amplifier from damage by a small discharge     11       Figure 4 – Measured current signal under –5,8 kV     14       Figure 5 – First measured current signal (< 1 min)					
Figure 4 – Measured current signal under –5,8 kV14Figure 5 – First measured current signal (< 1 min)	Figure	3 – Sample of circuit to protect the amplifier from damage by a small discharge			
Figure 5 – First measured current signal (< 1 min)					
Figure 6 – Measured current signal under –46,4 kV, after 1,5 h under high voltage	-	-			
Figure 7 – Measured current signal without applied voltage, after 1,5 h under high voltage	-				
voltage	•				
			. 16		
	Figure	8 – Internal electric field distribution under –5,8 kV	. 16		
	Figure	9 – Internal electric field distribution under –46,4 kV, at the initial state	.17		

Figure 10 – Internal electric field distribution under –46,4 kV, after 1,5 h under high voltage	17
Figure 11 – Internal electric field distribution without applied voltage after 1,5 h under high voltage	18
Figure A.1 – Comparison between practical and perfect pressure pulses	19
Figure A.2 – Original signal of the sample free of charge under moderate voltage	20
Figure A.3 – Comparison between original and corrected reference signals with a sample free of charge under moderate voltage	21
Figure A.4 – Electric field in a sample under voltage with space charge calculated from original and corrected signals	22
Figure A.5 – Geometrical characteristics of the reference signal for the correction coefficient estimation	23
Figure A.6 – Reference signal corrected with coefficients graphically obtained and adjusted	23
Figure A.7 – Electric field in a sample under voltage with space charge calculated with graphically obtained coefficient and adjusted coefficient	24
Figure B.1 – Voltage signals obtained from the oscilloscope by the amplifier with different amplifications	27
Figure B.2 – Current signals induced by the sample, considering the input impedance and the amplification of the amplifier	27
Figure B.3 – Relationship between the measured current peak of the first electrode and applied voltage	28
Table A.1 – Variants of symbols used in the text	24

#### INTERNATIONAL ELECTROTECHNICAL COMMISSION

### MEASUREMENT OF INTERNAL ELECTRIC FIELD IN INSULATING MATERIALS – PRESSURE WAVE PROPAGATION METHOD

#### FOREWORD

- 1) The International Electrotechnical Commission (IEC) is a worldwide organization for standardization comprising all national electrotechnical committees (IEC National Committees). The object of IEC is to promote international co-operation on all questions concerning standardization in the electrical and electronic fields. To this end and in addition to other activities, IEC publishes International Standards, Technical Specifications, Technical Reports, Publicly Available Specifications (PAS) and Guides (hereafter referred to as "IEC Publication(s)"). Their preparation is entrusted to technical committees; any IEC National Committee interested in the subject dealt with may participate in this preparatory work. International, governmental and non-governmental organizations liaising with the IEC also participate in this preparation. IEC collaborates closely with the International Organization for Standardization (ISO) in accordance with conditions determined by agreement between the two organizations.
- The formal decisions or agreements of IEC on technical matters express, as nearly as possible, an international consensus of opinion on the relevant subjects since each technical committee has representation from all interested IEC National Committees.
- 3) IEC Publications have the form of recommendations for international use and are accepted by IEC National Committees in that sense. While all reasonable efforts are made to ensure that the technical content of IEC Publications is accurate, IEC cannot be held responsible for the way in which they are used or for any misinterpretation by any end user.
- 4) In order to promote international uniformity, IEC National Committees undertake to apply IEC Publications transparently to the maximum extent possible in their national and regional publications. Any divergence between any IEC Publication and the corresponding national or regional publication shall be clearly indicated in the latter.
- 5) IEC itself does not provide any attestation of conformity. Independent certification bodies provide conformity assessment services and, in some areas, access to IEC marks of conformity. IEC is not responsible for any services carried out by independent certification bodies.
- 6) All users should ensure that they have the latest edition of this publication.
- 7) No liability shall attach to IEC or its directors, employees, servants or agents including individual experts and members of its technical committees and IEC National Committees for any personal injury, property damage or other damage of any nature whatsoever, whether direct or indirect, or for costs (including legal fees) and expenses arising out of the publication, use of, or reliance upon, this IEC Publication or any other IEC Publications.
- 8) Attention is drawn to the Normative references cited in this publication. Use of the referenced publications is indispensable for the correct application of this publication.
- 9) Attention is drawn to the possibility that some of the elements of this IEC Publication may be the subject of patent rights. IEC shall not be held responsible for identifying any or all such patent rights.

IEC TS 62836 has been prepared by IEC technical committee 112: Evaluation and qualification of electrical insulating materials and systems. It is a Technical Specification

This first edition of IEC/TS 62836 cancels and replaces the first edition of the Technical Report of IEC/TR 62836 published in 2013. It constitutes a technical revision.

The text of this Technical Specification is based on the following documents:

Draft	Report on voting
112/472/DTS	112/499/RVDTS

Full information on the voting for its approval can be found in the report on voting indicated in the above table.

The language used for the development of this Technical Specification is English.

This document was drafted in accordance with ISO/IEC Directives, Part 2, and developed in accordance with ISO/IEC Directives, Part 1 and ISO/IEC Directives, IEC Supplement, available at www.iec.ch/members\_experts/refdocs. The main document types developed by IEC are described in greater detail at www.iec.ch/standardsdev/publications.

The committee has decided that the contents of this document will remain unchanged until the stability date indicated on the IEC website under "http://webstore.iec.ch" in the data related to the specific document. At this date, the document will be

- reconfirmed,
- withdrawn,
- replaced by a revised edition, or
- amended.

IMPORTANT – The 'colour inside' logo on the cover page of this publication indicates that it contains colours which are considered to be useful for the correct understanding of its contents. Users should therefore print this document using a colour printer.

#### INTRODUCTION

High voltage insulating cables, especially high voltage DC cables, are subject to charge accumulation and this may lead to electrical breakdown if the electric field produced by the charges exceeds the electrical breakdown threshold. With the trend to multiply power plants, especially green power plants such as wind or solar generators, more cables will be used for connecting these power plants to the grid and share the electric energy between countries. Therefore, the materials for the cables, and even the structure of these cables, when considering electrodes or the junction between cables, need a standardized procedure for testing how the internal electric field can be characterized. The measurement of the internal electric field would give a tool for comparing materials and help to establish thresholds on the internal electric field for high voltage applications in order to limit breakdown risks as much as possible. The pressure wave propagation (PWP) method has been used by many researchers to measure the space charge distribution and the internal electric field distribution in insulators. However, since experimental equipment, with slight differences, is developed independently by researchers throughout the world, it is difficult to compare the measurement results between the different equipment.

The procedure outlined in this Technical Specification provides a reliable point of comparison between different test results carried out by different laboratories in order to avoid interpretation errors. The IEC has established a project team to develop a procedure for the measurement of PWP.

## MEASUREMENT OF INTERNAL ELECTRIC FIELD IN INSULATING MATERIALS – PRESSURE WAVE PROPAGATION METHOD

#### 1 Scope

This document provides an efficient and reliable procedure to test the internal electric field in the insulating materials used for high-voltage applications, using the pressure wave propagation (PWP) method. It is suitable for a sample with homogeneous insulating materials and an electric field higher than 1 kV/mm, but it is also dependent on the thickness of the sample and the pressure wave generator.

#### 2 Normative references

There are no normative references in this document.